

NOTE: PLEASE CONFIRM ALL PARTS SHOWN OR NOTED ARE PRESENT BEFORE STARTING.

## Parts List

BOX-1		
A. Base		X1
B. Pole Adapter		X1
C. Wire Collar (NOT NEEDED)		X2
D. Header Clip		X1

BOX-2		
E. Metal Wire Frame		X1
F. Center Pole		X2
G. Bearing Assembly (washer & ball bearing)		X1
H. Wire Head Sign Clip		X1

## Assembly Instructions


Step 1: Place the base on the floor and press the pole adapter into the center hole.



Step 2: Insert the center pole with flange into base until completely seated. See image below.



Step 3: Slide bearing assembly onto pole until it is seated on the flange.



Step 4: Slide the smaller end of the 2nd pole into the top of the flanged pole.



Step 5: Slide metal wire frame onto assembled pole.



Step 6: Place the header clip on top of the assembled poles.



The assembly is finished.



If you have any questions regarding our products, please visit us at [www.displays2go.com](http://www.displays2go.com) or contact D2G customer service.