




Scan QR code to visit product page

1. Lift bracket off post to best access screw head under nut.

Max Load: 8 Kgs

Part List:



A. 1 pc

B. M4x10 4 pcs

C. M5x16 2 pcs

D. 4 pcs

E. 4 pcs

F. 4 pcs

G. 1 pc



H. 1 pc

or 1. Screws supplied with stand.

2. Spacers, parts D/E/F, are used to allow screw B to tighten screen to bracket.


Adjust torque...if necessary

3.

Max Load: 8 Kgs

1. Lift bracket off post to best access screw head under nut.

Part List:



A. 1 pc

B. M4x10 4 pcs

C. M5x16 2 pcs

D. 4 pcs

E. 4 pcs

F. 4 pcs

G. 1 pc



H. 1 pc

or 1. Screws supplied with stand.

2. Spacers, parts D/E/F, are used to allow screw B to tighten screen to bracket.

Adjust torque...if necessary

3.