

GCH5740WT Assembly Instructions:

* PLEASE CONFIRM ALL PARTS SHOWN OR NOTED ARE PRESENT BEFORE STARTING. DO NOT DISCARD PACKING.

- Parts:** (1) Base
(1) Wire Frame
(1) Bearing Assembly
(1) Cotter Pin
(1) Washer
(1) Header Clip
(2) Poles (1 having a male end)

Assembly:

Step 1: Place the base on the floor, Insert pole with male end into the base until it is completely seated (male end facing up).



Step 2: Place Pin into pin hole (bend ends back using pliers).




Step 3: Place washer on top of the pin.



Step 4: Slide ball bearing onto the washer.



Step 5: Slide second pole onto the male end of the first pole.



Step 6: Slide wire frame over the assembled poles.



Step 6: Place header clip on top of the assembled poles.

