Portable Display Instructions



Step 1
Place ShowMax unit with wheels facing up and away from the front of the display table. Unlatch two panel latches and both bottom end cap latches.



Step 2 Open unit. Remove styrene header, lights and cords. Fold four end caps up.



Step 3
Grip each side of unit on outside near top of case, and lift up until case is vertical.



Step 4
Open outer panels, but leave angled to support display.



Step 5 Place header into two slots on backside of center panels.



Step 6 Mount light fixture by inserting base peg into hole on top of side panel.

