


LED QUEUE POLE TOPPER
SKU: QPSOLT4




PARTS LIST




A

Solar Topper *1



C

USB Charge Cable *1




B

Stanchion *1
(not included)


ASSEMBLY INSTRUCTIONS

STEP 1







Connect the Solar
Topper with the
stanchion

FINISHED



CONTACT INFORMATION:
www.displays2go.com
PHONE: 844-221-3388

PARTS LIST	USING INSTRUCTIONS		
 A	Mode 1 Press power button once--Turn on the light 		
Charging Method Method 1 USB charging Full charged:3-4hours charging  USB charge Method 2 Solar charging Full charged: 60-80 hours 	Mode 2 Press power button twice--Turn on the light sensor (blue indicator light on) which automatically turns lights on when no light / low light detected   blue indicator light on 		
	Mode 3 Press power button third--Turn off the light 		