




Step
1




Step
2




Step
3




Step
4




Step
5




Step
6




Step
7




Step
8




Step
9



Step
10



Step
11



A			4	L		M8x14mm	4	X		1	
B		M10x35mm	2	M		φ 20x φ 10mm	8	Z		M8x16mm	4
C		φ 30x φ 10mm	2	N			4				
D		5.9mm	1	O		M8	4	B1		2	
E		M5x18mm	1	P			2	C1		1	
F		7.9mm	1	Q			1	D1		M4x25mm	2
G			1	R			1	E1		M6mm	6
H		3mm	1	S			1	F1			1
I		φ 20x φ 8mm	8	T			1	G1			1
J		M6x30mm	6	U			2	H1		φ 16x φ 6mm	1
K		2.5mm	1	V			1				